



In re Patent of: Examiner: Huyen Le Ngo MASANORI TAKAHASHI ET AL. Group Art Unit: 2871 Appl. No.: 08/814,082 Filed: March 10, 1997 For: DRIVE CIRCUIT CONNECTION STRUCTURE AND DISPLAY APPARATUS INCLUDING THE Certificate CONNECTION STRUCTURE AUG 1 3 2004 U.S. Patent No.: 6,738,123 B1 of Correction Issued: May 18, 2004 August 9, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/11/2004 JBALIHAN 00000111 6738123

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentees Registration No.: 24613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

NY\_MAIN 445043v1

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,738,123 B1

DATED

May 18, 2004

INVENTOR(S) :

MASANORI TAKAHASHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 2

Line 1, "or" should read --for--.

### COLUMN 6

Line 51, "area1" should read -- areal--.

# **COLUMN 7**

Line 66, "canning" should read --scanning--.

# **COLUMN 8**

Line 43, "area1" should read -- areal--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,738123 B1</u>

No. of add'l. copies @ 30¢ per page

➡> \_\_\_

Form PTO 1050 (Rev. 3-82) NY Main-445070

# Staple Here Only! Staple Here Unly!

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,738,123 B1

DATED

May 18, 2004

INVENTOR(S) :

MASANORI TAKAHASHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 9

Line 17, "ends of the conductors" should be deleted; and Line 18, "conductor" should be deleted.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. US 6,738123 B1

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) NY Main-445070

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,738,123 B1

DATED

May 18, 2004

INVENTOR(S) :

MASANORI TAKAHASHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 2

Line 1, "or" should read --for--.

### **COLUMN 6**

Line 51, "area1" should read -- areal--.

### **COLUMN 7**

Line 66, "canning" should read --scanning--.

# **COLUMN 8**

Line 43, "area1" should read -- areal--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,738,123 B1</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY Main-445070

# Staple Here Only! Staple Here Only!

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,738,123 B1

**DATED** 

May 18, 2004

INVENTOR(S) :

MASANORI TAKAHASHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# **COLUMN 9**

Line 17, "ends of the conductors" should be deleted; and Line 18, "conductor" should be deleted.

### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. US 6,738,123 B1

No. of add'l. copies @ 30¢ per page

<u></u> -